



8/18/2009

Boiler condition: Glow maintenance


Actual power stage: 4 of 5

Print picture

Print report

## FOR BOILER WATER / BACK BOILER WATER TEMPERATURES

8/18/2009 8:31:11 AM



Trend	Tag connection	Value	Date/Time
FLOW_WATER_TEMPERATURE	IW_VLT_KESSEL	95.200000	8/18/2009 5:31:23:124 AM
BACK_WATER_TEMPERATURE	IW_RLT_KESSEL	94.200000	8/18/2009 5:31:25:453 AM

タグ名

BACK